

## Wellsite Supervision of Wireline Operations

### 4 Ways ResTech Can Improve Your Logging Job

1. **Cost Control**
2. **Quality Control**
3. **Communications**
4. **Log Interpretation**

#### Cost Control

- > Recommend the most cost effective logging program
- > Verify the wellsite efficiency of the wireline contractor and note instances where reimbursement is due
- > Insure that you only run the services you need !

#### Quality Control

- > Insure safety compliance
- > Verify calibrations
- > Verify new log data with offset well data
- > Verify log repeatability
- > Verify depth control.
- > Verify logging procedure compliance
- > Record an event log

#### Communications

- > Pre-job client meeting or briefing by phone
- > Pre-job consultation with wireline district & personnel
- > Coordinate wireline operations at the rig
- > Provide immediate notice to Company Man and Client for any problems encountered
- > Fax 1 " downlog and 1" & 5" uplog to client & partners
- > Provide qualitative assessment of the prospect
- > Recommend additional evaluation procedures
- > Provide progress reports at regular intervals
- > Verify field prints for compliance with client standards
- > Expedite field print delivery to client & partners
- > Deliver reports and job assessment at post job meeting

#### Log Interpretation

- > Complete Petrophysical Evaluation of the prospect by the experienced ResTech team in Houston